

		Steam Inlet Pressure (psi)									
		5		10		15		30		50	
Temperature Rise (°F)	Model Prefix	Recovery (gals per min)	Steam Flow (lbs per hr)	Recovery (gals per min)	Steam Flow (lbs per hr)	Recovery (gals per min)	Steam Flow (lbs per hr)	Recovery (gals per min)	Steam Flow (lbs per hr)	Recovery (gals per min)	Steam Flow (lbs per hr)
40 to 120	10	10	380	10	400	10	420	12	470	13	530
	20	19	760	20	800	20	840	23	940	25	1050
	40	37	1510	39	1600	40	1680	45	1880	50	2100
	60	Contact factory	Contact factory	58	2390	60	2510	67	2820	74	3150
	80	Contact factory	Contact factory	Contact factory	Contact factory	80	3350	89	3760	99	4200
40 to 140	10	7	350	7	370	8	390	9	440	10	500
	20	14	690	14	730	15	770	17	880	19	990
	40	27	1370	28	1460	30	1540	33	1750	37	1970
	60	Contact factory	Contact factory	42	2180	45	2300	50	2620	55	2950
	80	Contact factory	Contact factory	Contact factory	Contact factory	59	3070	66	3490	74	3930
40 to 160	10	5	310	6	330	6	350	7	400	8	460
	20	10	610	11	650	12	700	13	800	15	910
	40	20	1210	21	1300	23	1390	26	1600	29	1820
	60	30	1820	32	1950	34	2080	38	2400	43	2730
	80	Contact factory	Contact factory	42	2600	45	2770	51	3190	57	3640

- Contact PVI if steam pressure and /or required temperature rise differ from those listed.