





# PIPING GUIDE: TWO STORAGE WATER HEATERS WITH TWO SUPPLEMENTAL STORAGE TANKS

NOTE: TURBOPOWER 99 water heaters have building return connection different than shown here. Consult PVI for proper piping illustration.

	Union
	Isolation Ball Valves
	Check Valve
	T&P Relief Valve (pipe in accordance with local codes, or direct to drain with no valves or restrictions)

